To: Tulis, Dana[Tulis.Dana@epa.gov]; Ostrander, David[Ostrander.David@epa.gov] Crossland, Ronnie[Crossland.Ronnie@epa.gov]; Smith, Monica[smith.monica@epa.gov]; Cc: Calanog, Steve[Calanog.Steve@epa.gov]; Meer, Daniel[Meer.Daniel@epa.gov]; Davis, Joe[Davis.Joe@epa.gov]; Foster, Althea[Foster.Althea@epa.gov]; Hayes, Mark[hayes.mark@epa.gov]; Martin, John[martin.john@epa.gov] From: Barry, Michael Sent: Mon 9/28/2015 6:13:16 PM Subject: GKMR IC Proposal to Address Sediment Response Related Damages Criteria for Response Related Damages 28Sep2015.pdf All: Incident command is proposing to the R8 RICT and HQ OEM to perform some limited repair to response related damages to address sediment deposition in low flow residential areas. Attached is a more detailed rationale and criteria when to perform this repair. We recognize the presence setting aspects of this proposed action and that it may impact downstream areas in R6 and R9, thus will also coordinate with R6 and R9. Thanks for your consideration, Mike Mike Barry | Cell: 617.680.5466 | barry.michael@epa.gov 9/24 - 10/7/2015: **Incident Commander** Gold King Mine Response Durango, CO Permanent:

Team Leader On-Scene Coordinator,

Emergency Response & Planning Branch

EPA Region 1, 5 Post Office Square, Suite 100 (OSRR02-2), Boston, MA, 02109